


CORNER RECORD

5S 33-17-3

Document Number _____

City of _____ County of MONO, California

Brief Legal Description LOT 11 TRACT NO. 37-15, SEC 22, T. 5S, R. 33E, M. 12, 13, 14



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey 2-14-01

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


FND 2" IP "LS 3462" @ NW LOT 11, NE LOT 11, W & PT LOT 11 & NE LOT 12. ALSO
FND 2" IP "LS 3462" @ SE LOT 12 & SE LOT 11 WHICH WERE USED TO PROPORTION
THE SW COR LOT 11

A description of the physical condition of the monument as found and as set or reset: SET 3/8" REBAR ECAP
MARKED "LS 4537" @ SW COR LOT 11

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on March 10 2001

Signed [Signature] L.S. or R.C.E. Number 4587



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 04-14 2005 and examined
 and filed 07-01 2005

Signed [Signature] Title Mon County Sur.



County Surveyor's Comment _____